HABS CAL 19-SAUG, 1A-

## HISTORIC AMERICAN BUILDINGS SURVEY

## INDEX TO PHOTOGRAPHS

Harry Carey Ranch, Ranch House (Building No. 5) 28515 San Francisquito Canyon Road Saugus Los Angeles County California HABS No. CA-2712-A

## William B. Dewey, Photographer

November 2000

CA-2712-A-1	GENERAL VIEW OF BUILDING 5 FROM DRIVEWAY, SHOWING FRONT PORCH AND FENCE; CAMERA FACING WEST.
CA-2712-A-2	VIEW OF EAST FAÇADE; CAMERA FACING WEST.
CA-2712-A-3	VIEW OF WEST SIDE OF RANCH HOUSE, SHOWING COURTYARD AND BEDROOM WINGS; CAMERA FACING SOUTHEAST.
CA-2712-A-4	OBLIQUE VIEW OF NORTH SIDE, SHOWING KITCHEN CHIMNEY; CAMERA FACING SOUTHEAST.
CA-2712-A-5	VIEW OF SOUTH SIDE OF RANCH HOUSE; CAMERA FACING NORTHWEST.
CA-2712-A-6	VIEW OF SOUTH SIDE OF RANCH HOUSE; CAMERA FACING NORTH.
CA-2712-A-7	DETAIL OF EXTERIOR WALL WEST OF KITCHEN ENTRANCE, SHOWING ADOBE CONSTRUCTION AND EXTERIOR FINISH; CAMERA FACING EAST.
CA-2712-A-8	DETAIL OF FRONT PORCH, MAIN ENTRANCE, AND SOUTH BEDROOM WING ENTRANCE; CAMERA FACING SOUTHWEST.
CA-2712-A-9	OBLIQUE VIEW OF FRONT PORCH; CAMERA FACING NORTH.
CA-2712-A-10	DETAIL OF MAIN ENTRANCE, WITH NICHE TO LEFT; CAMERA FACING WEST.

HARRY CAREY RANCH Ranch House (Building 5) HABS No. CA-2712-A INDEX TO PHOTOGRAPHS (Page 2)

CA-2712-A-11	DETAIL OF FRENCH DOORS, SOUTHERNMOST EXTERIOR DOOR FROM DINING ROOM; CAMERA FACING EAST.
CA-2712-A-12	DETAIL OF WINDOW, SOUTHERNMOST WINDOW IN WEST END OF NORTHERN BEDROOM WING; CAMERA FACING EAST.
CA-2712-A-13	GENERAL VIEW OF HOUSE, GARDEN AND FENCE, WITH OLD FARM EQUIPMENT NEAR DRIVEWAY; CAMERA FACING WEST.
CA-2712-A-14	GENERAL VIEW FROM GARDEN; CAMERA FACING NORTHEAST.
CA-2712-A-15	INTERIOR VIEW FROM EAST BEDROOM (NORTH WING) THROUGH BATHROOM TO WEST BEDROOM; CAMERA FACING WEST.
CA-2712-A-16	INTERIOR VIEW FROM DINING ROOM INTO LIVING ROOM; CAMERA FACING SOUTH.
CA-2712-A-17	INTERIOR DETAIL SHOWING A TYPICAL INTERIOR DOOR (BETWEEN EAST BEDROOM, NORTH WING, AND BATHROOM); CAMERA FACING WEST.
CA-2712-A-18	INTERIOR DETAIL OF EAST BEDROOM, SOUTH WING; CAMERA FACING SOUTHEAST.
CA-2712-A-19	INTERIOR DETAIL OF MIDDLE BEDROOM, SOUTH WING; CAMERA FACING SOUTH.
CA-2712-A-20	INTERIOR DETAIL OF FLAT ARCH BETWEEN LIVING ROOM AND DINING ROOM; CAMERA FACING NORTH.
CA-2712-A-21	INTERIOR DETAIL OF EAST BEDROOM, SOUTH WING, SHOWING YUCCA MURAL; CAMERA FACING SOUTHWEST.
CA-2712-A-22	INTERIOR DETAIL OF WEST BEDROOM, NORTH WING, SHOWING COWBOY MURAL; CAMERA FACING NORTHWEST.
CA-2712-A-23	INTERIOR DETAIL OF, CEILING OF EAST BEDROOM, NORTH WING, SHOWING PART OF MOUNTAIN LION MURAL; CAMERA FACING NORTHEAST.
CA-2712-A-24	INTERIOR DETAIL OF FIREPLACE AND CATTLE DRIVE MURAL IN LIVING ROOM; CAMERA FACING WEST.

HARRY CAREY RANCH Ranch House (Building 5) HABS No. CA-2712-A INDEX TO PHOTOGRAPHS (Page 3)

CA-2712-A-25	INTERIOR DETAIL OF FIREPLACE IN WEST BEDROOM, SOUTH WING; CAMERA FACING NORTHWEST.
CA-2712-A-26	INTERIOR DETAIL OF KITCHEN, WITH FIREPLACE AT FAR LEFT; CAMERA FACING SOUTHEAST.
CA-2712-A-27	INTERIOR DETAIL OF CABINETS IN KITCHEN; CAMERA FACING SOUTHEAST.